



**WEBB DIVISION**

A division of Marmon Industries, Inc.  
2310 Industrial Drive, S.W.  
Cullman, Alabama 35055  
(205) 739-6660

September 20, 1985

**SERVICE BULLETIN (NO. 6)**

**(NOTICE OF SUPERSESSION)**

**16175 RIM CLAMP**

**REPLACEMENT CLAMP: 16177**

As a part of our continuing effort toward product improvement, we have replaced our 16175 rim clamp with our 16177 rim clamp. This change is made to improve the seating of the rim nut on the clamp face.

This supersession will take effect with depletion of inventory on the 16175 clamp.

Interchangeability of the clamps is not affected by this change.