



SERVICE BULLETIN #108

03/10/2012

54251 Rotor

Because of a decline in sales, the 54251 Rotor is being discontinued. Please mark your records to indicate the subject part number is obsolete effective immediately with no replacement.

If you have any questions regarding this change, please contact our sales department at sales@webbwheel.com or technical service department at engineering@webbwheel.com.