




SERVICE BULLETIN #121

1/23/14

4023 Aluminum Disc Wheel Hub

The 4023 Aluminum Disc Wheel Hub is obsolete with no direct replacement. We do, however, recommend a replacement: the 10-stud 2023 Ductile Iron Disc Wheel Hub. There are no other component changes required for this interchange. The same assembly options are available for the 2023 Disc Wheel Hub as were previously offered with the 4023 Disc Wheel Hub. If you have any questions, please contact the Webb Wheel Engineering Department via email to engineering@webbwheel.com or call 256-736-6356.



4023T Bill of Materials			
Item	Part No.	Description	Qty.
1	4023T	Aluminum Disc Wheel Hub	1
2	HM212011	Outer Bearing Cup	1
3	HM218210	Inner Bearing Cup	1

2023A Bill of Materials			
Item	Part No.	Description	Qty.
1	2023A	Ductile Iron Disc Wheel Hub	1
2	HM212011	Outer Bearing Cup	1
3	HM218210	Inner Bearing Cup	1