



WEBB WHEEL PRODUCTS, INC.

2310 Industrial Drive, S.W.

Cullman, Alabama 35055

(205) 739-6660

FAX: (205) 739-6246

November 8, 1993

SERVICE BULLETIN (No. 30)

INTERCHANGE AND SPECIFICATION CORRECTION

on

WEBB 63650 and 63652 BRAKE DRUMS

This bulletin is issued to correct and clarify information currently shown on Bolt Holes and Interchanges for the above brake drums, in our current Brake Drum Catalog TB793BD.

Both the 63650 and 63652 are shown in the catalog as interchanging with Dayton drum 122924. The interchanges should be corrected as follows:

63750 Interchanges with Dayton 120582

63652 Interchanges with Dayton 122924


All other interchanges shown in the catalog are correct.

The BOLT HOLE information shown in the catalog is clarified as follows:


63650 Has 6 holes .81 in size — Holes are equally spaced

63652 Has 6 holes .81 in size — Holes are located in 3 pairs, 2 holes each

63650



63652



Please correct your catalogs to show the above information.