



WEBB WHEEL PRODUCTS, INC.

2310 Industrial Drive, S.W.
Cullman, Alabama 35055
(205) 739-6660
FAX: (205) 739-6246

April 21, 1995

SERVICE BULLETIN NO. 40

This bulletin is issued to advise you of several products which are being discontinued as a part of our product line.

The products being discontinued will be obsolete as inventory is depleted. Please continue to order the product being discontinued. You will be advised with entry of your order when inventory is depleted and that the replacement product should be ordered.

Shown below is a list of products you may purchase in place of the products being obsoleted.

We appreciate your assistance. Should you have any questions regarding this bulletin, please let us know.

Being Obsoleted	Use to Replace
1000 Hub uses 60876 drum	1020 Hub uses 66893 drum
1002 Hub uses serrated stud	1001 Hub uses shoulder stud
1222 Hub uses serrated stud	1221 Hub uses shoulder stud
1300 Hub uses 60876 drum	1320 Hub uses 66893 drum
1523 Ball Seat Mount Hub	2523 Latest design — can be used with Ball Seat wheels or Hub Piloted wheels when ordered with proper stud.
1620 Ball Seat Mount Hub	2643 Latest design — can be used with Ball Seat wheels or Hub Piloted wheels when ordered with proper stud.
1621 Ball Seat Mount Hub	2643 Latest design — can be used with Ball Seat wheels or Hub Piloted wheels when ordered with proper stud.
960 Spoke Wheel	No Replacement
9561 Spoke Wheel	No Replacement