

WEBB WHEEL PRODUCTS, INC.

2310 Industrial Drive, S.W. Cullman, Alabama 35055 (205) 739-6660 FAX: (205) 739-6246

January 5, 1996

SERVICE BULLETIN NO. 40A

This bulletin is issued to correct portions of our Service Bulletin No. 40 issued on April 21, 1995.

Service Bulletin No. 40 was issued to advise you of several products which are being discontinued as a part of our product line.

The products being discontinued will be obsolete as inventory is depleted. Please continue to order the product being discontinued. You will be advised with entry of your order when inventory is depleted and that the replacement product should be ordered.

Shown below is a list of products you may purchase in place of the products being obsoleted.

We appreciate your assistance. Should you have any questions regarding this bulletin, please let us know.

BEING OBSOLETED		USE TO REPLACE		
	1000	HUB USES 60876 DRUM	1020	HUB USES 66893 DRUM REPLACE AS ASSEMBLY ONLY
	1002	HUB USES SERRATED STUD	1001	HUB USES SHOULDER STUD DRUMS INTERCHANGEABLE
	1222	HUB USES SERRATED STUD	1221	HUB USES SHOULDER STUD DRUMS INTERCHANGEABLE
	1300	HUB USES 60876 DRUM	1320	HUB USES 66893 DRUM REPLACE AS ASSEMBLY ONLY
	1523	BALL SEAT MOUNT HUB	2523	LATEST DESIGN — CAN BE USED WITH BALL SEAT WHEELS OR HUB PILOTED WHEELS WHEN ORDERED WITH PROPER STUD. REPLACE AS ASSEMBLY ONLY
	1620	BALL SEAT MOUNT HUB	2643	LATEST DESIGN — CAN BE USED WITH BALL SEAT WHEELS OR HUB PILOTED WHEELS WHEN ORDERED WITH PROPER STUD. REPLACE AS ASSEMBLY ONLY
	1621	BALL SEAT MOUNT HUB	2643	LATEST DESIGN — CAN BE USED WITH BALL SEAT WHEELS OR HUB PILOTED WHEELS WHEN ORDERED WITH PROPER STUD. REPLACE AS ASSEMBLY ONLY
	960	SPOKE WHEEL		NO REPLACEMENT
	9561	SPOKE WHEEL		WAS NO REPLACEMENT ON SERVICE BULLETIN NO. 40. PART WILL REMAIN AVAILABLE AND NOT BE DISCON- TINUED.