



WEBB WHEEL PRODUCTS, INC.
2310 Industrial Drive, S.W.
Cullman, Alabama 35055
(256) 739-6660
FAX: (256) 739-6246

9/9/02

SERVICE BULLETIN # 73

This Service Bulletin is issued to announce a change to the "Bolt Hole" size on the brake drums listed below from .94" to 1.00".

60545B	61988B	65176F	65670F	66665B	66864B
60864B	61988F	65177B	66353B	66814B	66864F
61510B	61991B	65177F	66353F	66814F	66866B
61510F	61991F	65179B	66364B	66823F	66866D
61518B	63645F	65179F	66364D	66824B	66871B
61527B	64125F	65183B	66364F	66824F	66871F
61567B	65153B	65183D	66366B	66825B	66873F
61567F	65153F	65183F	66366F	66826B	66874B
61577B	65155B	65183U	66374B	66826F	66874F
61577F	65162B	65545B	66374F	66827B	66884B
61581F	65162F	65545F	66661B	66827F	66884D
61950B	65163B	65555B	66661F	66829F	66884F
61950D	65163F	65555D	66663B	66834F	68985B
61950F	65170B	65555F	66663F	66843B	68985F
61950U	65170F	65555U	66664B	66854B	
61951B	65176B	65670B	66664F	66854F	

The purpose of this change is to eliminate the possibility of interference when Webb brake drums are installed on hubs produced by other manufacturers.

If any questions arise with regards to this or any other information regarding our products, please feel free to contact our Engineering or Sales Department at the address and phone number shown on this bulletin or at sales@webbwheel.com.