



WEBB WHEEL PRODUCTS, INC.  
 2310 INDUSTRIAL DR. S.W. CULLMAN, AL 35055  
 Phone: 256-739-6660 Fax: 256-739-6246  
 www.webbwheel.com

9-15-03

## SERVICE BULLETIN # 79

The following products have become obsolete. We have suggested a replacement where available.

<u>Part Number</u>	<u>Assemblies Affected</u>	<u>Assemblies Affected</u>	<u>Assemblies Affected</u>	<u>Assemblies Affected</u>
100274	25801LXFRT			
100275	25801LXFLT			
101121	26181RF27	26181RF27T		
101122	25261RZ23 25281RZ23T	25261RZ23T 25281RZ24T	25281--23	25281RZ23
16227-N				
178950	10209--DR 25201--SR 25231GSSR 25301TMSRT	20231UQDR-10 25201--SRT 25231RXSR 25601XVDR	20231UQDRT-10 25201GSSRT 25231RXSR-10 40231ZQDR-10	20231UQDRT-26 2501KRSRT 25301KVSRT 40231ZQDR-72
178951	10209-DL 20231UQDR-10 25201-SR 25201KRSRT 25301TMSRT 40231ZQDR-10	10209-DR 20231UQDRT-10 25201-SRT 25201KRSRT 25301TMSRT 40231ZQDR-72	20231UQDL-10 25201-SL 25201GSSRT 25301KVSLT 40231ZQDL-10	20231UQDLT-10 25201-SLT 25201GSSRT 25301KVSRT 40231ZQDL-72
179920	25281RZ24 25281RZ24T-10 26081DS24T-10 26081DS28T-10 26181PF23 26181RF24-10	(Replacement 25281RZ4) (Replacement 25281RZ4T-10) (Replacement 26081DS4T-10) (Replacement 26081DS8T-10) (Replacement 26181PF3) (Replacement 26181RF4-10)	25281RZ24-10 26081DS23T 26081DS27T 26181PE23 26181RF23T 26431DV25T	(Replacement 25281RZ4-10) (Replacement 26081DS3T) (Replacement 26081DS7T) (Replacement 26181PE3) (Replacement 26181RF3T) (Replacement 26431DV5T)
179955	222 25281TG32T-10 25281TG34T-10	(Replacement 25281TG2T-10) (Replacement 25281TG4T-10)		
2570F	25701-3	25701XU3	25701XU4-10	