



SERVICE BULLETIN # 98

8/12/08

Interchange Clarification

Recently, customers have brought a potential interchange error with an ArvinMeritor 122921 drum, versus a Webb drum 65546B regarding the hole size. Interchange accuracy is important to us here, so we purchased the competitor's drum to investigate and here are the findings:

The competitor's drum has two part numbers cast into it, as well as the hole size that corresponds with each drum (122921 & 123396). We have determined that the interchanges on the internet and our catalogs are correct.

122921 = 65546B - .81 diameter holes, 8.75 pilot



123396 = 61527B - 1.00 diameter holes, 8.78 pilot



If you have any questions regarding this bulletin, please contact technical service at (256) 775-7514 or engineering@webbwheel.com.