

## WEBB DIVISION

OF MARMON INDUSTRIES, INC.

## **DIVISION OFFICES**

510 Indianapolis Avenue - Post Office Box 8 Lebanon, Indiana 46052 - Phone: 317/482-4070

## **NEW PRODUCTS**

BULLETIN

NO. 32

Date Available

October, 1980

In our continuing effort to be your full line supplier, we are proud to announce this new addition to our line.

HUB PART NUMBER BRAKE DRUM
PART NUMBER & SIZE

1251

 $63630 - 12\frac{1}{4} \times 5\frac{1}{2}$ 

INNER CUP OUTER CUP #653 HM212011  $63631 - 12\frac{1}{4} \times 7\frac{1}{2}$ 

**DESCRIPTION:** 

10 Stud 8 3/4 Bolt Circle Hub & Drum Assembly for 15" Disc · Wheel

**Applications** 

**AXLE APPLICATIONS:** 

Rockwell: TK Series Axles, TKL, TL, TLD

Eaton - T18C, C, CE, C2, E, 22L

Dana - K-20, K21

Standard Forge - A19S

Clark - NDS

Part Number	Description	Drum Size	Suggested List Price w/F.E.T.
1251 <b>.</b> -A	Service Assembly		\$187.98
1251 <b>3</b> BLA	1251 Hub 63630 Drum	121/4 x 51/2	\$290.82
1251 <b>9</b> CLA	1251 Hub 63631 Drum	121/4 x 71/2	\$302.81

Note: 6 Stud 8<sup>3</sup>/<sub>4</sub> Bolt Circle Hub also Available. See New Product Bulletin #31 for RN Axle Type Applications.

MARMON A Member of The Marmon Group of Companies