



**WEBB WHEEL PRODUCTS, INC.**  
2310 Industrial Drive, S.W.  
Cullman, Alabama 35055  
(256) 739-6660  
FAX: (256) 739-6246

12/18/01

## **SERVICE BULLETIN # 69**

### **OBSOLETE HUBS & SPOKE WHEELS**

Due to castings no longer being available, it has become necessary to change the status of some of our products.

The following products are either obsolete or will become obsolete during the next few months with depletion of inventory.

We are suggesting a replacement where available.

1622 Hub	Available as service replacement (with ABS ring) only. Obsolete – no replacement when inventory is depleted.
1623 Hub	Available as service replacement (with ABS ring) only. Obsolete – no replacement when inventory is depleted.
2510 Hub	Obsolete with no replacement.
2523 Hub	Available as service replacement only. Use 2520 for new production or service when 2523 inventory is depleted. Drums are interchangeable.
2528 Hub	Available as service replacement only. Use 2526 for new production or service when 2528 inventory is depleted. Drums are interchangeable.
5380 Spoke Wheel	When inventory is depleted, use 5580 for service or new production. Drums are interchangeable (5-Hole Pattern).
5520 Spoke Wheel	Available as service replacement only-Will become obsolete with no replacement when inventory is depleted.
5582 Spoke Wheel	Obsolete. Use 5682 for service or new production. Drums are interchangeable.
5680 Spoke Wheel	When inventory is depleted, use 5580 for service or new production. Drums are interchangeable (5-Hole pattern).

7000 Spoke Wheel	When inventory is depleted, use 7015 for service or new production. When replacing the 7000 in service, complete assembly must be replaced. Drums are not interchangeable.
7522 Spoke Wheel	When inventory is depleted, use 7622 for service or new production. Drums are interchangeable.
8322 Spoke Wheel	When inventory is depleted, use 8522 for service or new production. Drums are interchangeable.
3525 Spoke Wheel	Obsolete with no replacement.
3550 Spoke Wheel	When inventory is depleted, use 3560 for service or new production. Drums are interchangeable.
9562 Spoke Wheel	Will become obsolete – no replacement when inventory is depleted.
9661 Spoke Wheel	Will become obsolete – no replacement when inventory is depleted.
9662 Spoke Wheel	Will become obsolete-no replacement when inventory is depleted.

If you have any questions regarding this change, please contact us at the address and phone number shown in this bulletin or at [sales@webbwheel.com](mailto:sales@webbwheel.com).